MATERIAL SAFETY DATA SHEET

For Coatings, Resins and Related Materials (Approved by U.S. Dept. of Labor "Essentially Similar" to Form OSHA-20)

DATE OF PREP. JANUARY 16, 1995 NPCA HMIS H=0 F=0 R=0						
Section 1						
Manufacturer's Name: CRAIN CUTTER COMPANY, INC. Address: 1155 WRIGLEY WAY, MILPITAS, CA 95035 Emergency Telephone Number: 408/946-6100 Product Class: HOT MELT CARPET SEAM TAPE Trade Name: CARPET SEAM TAPE Manufacturer's Code Identification: #923, 927, 928, 929						
Section II - HAZARDOUS INGREDIENTS						
INGREDIENT	NTP/IARC/ OSHA CARC.	PERCENT	TL\ PPM	V MG/M	LEL	VAPOR PRESSURE
NONE						
Section III - PHYSICAL DATA						
BOILING RANGE: N/A PERCENT VOLATILE BY VOLUME: N/A VAPOR DENSITY: N/A EVAPORATION RATE: N/A WEIGHT PER GALLON: N/A						
Section IV -FIRE AND EXPLOSION HAZARD DATA						
DOT CATEGORY: Not regulatedFLASH POINT: 274°C (525°F)LEL:EXTINGUISHING MEDIA: Water Spray; Dry Chemical; C02UNUSUAL FIRE AND EXPLOSION HAZARDS: NoneEXPLOSION HAZARDS: NoneSPECIAL FIRE-FIGHTING PROCEDURES: Wear self-contained breathing apparatus and protective clothing to prevent contact with skin and eyes.EXPLOSION HAZARDS: NONE						

Section V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE: NE

EFFECTS OF OVEREXPOSURE: Inhalation - none expected; eyes - none expected.

EMERGENCY AND FIRST AID PROCEDURES: If burned by contact with molten materials, cool as quickly as possible with water and see a physician for treatment of burn. Note to physicians: the burns should be treated as thermal burns. Products are polymers of low toxicity; therefore, there is no urgent need to remove them from the skin because of concern about toxicity.

Section VI - REACTIVITY DATA

STABILITY: UNSTABLE STABLE INCOMPATIBILITY (material to avoid): Oxidizing material HAZARDOUS DECOMPOSITION PRODUCTS: Combustion will produce CO₂ and probably CO. HAZARDOUS POLYMERIZATION: MAY OCCUR WILL NOT OCCUR CONDITIONS TO AVOID:

Section VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Molten material - allow to cool and scrape-up.

WASTE DISPOSAL METHOD: Incineration or landfill - observe all federal, state and local laws concerning health and environment.

Section VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION: None should be needed.

VENTILATION: Local exhaust, if needed, to control fumes from heated material.

PROTECTIVE GLOVES: Should be worn to protect from thermal burns.

EYE PROTECTION: Safety glasses should be worn in any type of industrial operation.

OTHER PROTECTIVE EQUIPMENT: None required.

Section IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: None needed.

OTHER PRECAUTIONS: Avoid skin contact with molten material; otherwise, none needed.